## *Gems & Gemology* Data Depository: Durability and stability of the treatment in Be lattice diffusion—treated orange to pinkish-orange sapphires.<sup>a</sup>

Test	Procedure	Result
Ultrasonic cleaning	Placed in ultrasonic cleaner containing a solution (10%) of commercial jewelry cleaner (Health Sonics Corp.) and water for 45 minutes at a temperature of approximately 75°F.	No effect on treatment
Steam cleaning	Steam cleaner with pressure at 80 psi, ring-set stones placed one-half to one inch from the nozzle for approximately 45 seconds.	No effect on treatment
Heat and chemicals from jewelry repair	bOne prong tip sawed off and retipped with 14K white gold wire and 14K white hard solder (melting point approximately 1456°F) without any borax-containing fire coating on stone (the ring and stone were first fire coated with a boric acid/methyl alcohol solution; then a small paintbrush dipped in water was carefully used to remove all of the fire-coat from the stone). After retipping, the stone was removed from the mounting and carefully examined under magnification.	No effect on treatment
	bThe stone was reset in the same 14K white gold ring. Another prong tip was removed by grinding; stone and mounting was fire coated with boric acid/methyl alcohol solution and prong was retipped (this time without removing the fire coat from the stone) with 18K white gold wire and 18K white hard solder (melting point 1513°F). After retipping, the stone was removed from the mounting and carefully examined under magnification.	No effect on treatment (except for a very small area showing extremely minor etching under the prong that was retipped)
	<sup>c</sup> The stone-set ring was encased in "jet-set" and allowed to cool. "Jet-set" is a moldable plastic when at temperatures around 220°F, and hard when cool (at room temperature).	No effect on treatment
	<sup>c</sup> All six prongs on the stone-set 14K yellow gold ring were ground down; stone and mounting was fire coated with boric acid/methyl alcohol solution and prong was retipped (without removing the fire coat from the stone) with 14K yellow gold wire and 14K yellow hard solder (melting point approximately 1398°F). After retipping, the stone was removed from the mounting and carefully examined under magnification.	No effect on treatment
Rhodium electroplating	dThe stone-set ring was cleaned, then flash rhodium electroplated for five minutes at 6 volts, then 10–15 seconds at average of 3 volts; two-step plating procedure repeated, followed by second cleaning.	No effect on treatment
Laser welding	<sup>b</sup> The stone-set ring was welding at one prong using a Laser Star Workstation CPP standard model #501-6001 laser welding	No effect on treatment

machine (at normal settings for soldering gold).	
bThe stone-set ring was intentionally hit in the same area with the laser at a 45° angle on the table three separate times.	A large area on the pavilion, directly under where the laser struck the stone, was severely burned (surface-reaching cracks). No damage was observed on table. (This damage would have also occurred on a natural or heat-treated sapphire.)

<sup>&</sup>lt;sup>a</sup>All tests performed by Don and Corey Johnson, Eaton-Turner Jewelry, Helena, Montana.

Tests and results are for all 3 stones unless otherwise indicated.

<sup>&</sup>lt;sup>b</sup>1.12-ct medium dark pinkish-orange oval mixed-cut from Thailand.

c0.43-ct dark orange oval mixed-cut from Thailand.
d0.83-ct intense reddish-orange princess-cut from Thailand.